

=====

HITACHI エンタープライズサーバEP8000 シリーズ マシンコード更新手順

=====

DATドライブ(DAT-72 SCSI)ファームウェア変更内容と来歴

ファームウェア変更内容と来歴	
B015	信頼性向上 (1)Internal Drive Self Test Implemented (2)Request Sense flags to indicate state of drive/media (3)Added additional information to the tape drive internal log.
B014	信頼性向上 (1)Request cleaning when a bad tape fails to load. (2)Improve Reset and Abort handling. (3)Fix causes of read and read filemark errors. (4)Change to not eject tapes in a drive when microcode download is done. (This will take effect after the microcode is downloaded)
B013	信頼性向上 (1)Fix to report any errors on rewind that were previously not reported. (2)Change time for holding the eject button for emergency/forced eject from 5 seconds to 20 seconds. (3)Fix occasional formatting issue with 2 partition tape.
B012	信頼性向上 (1)Additional modifications to the tape drive diagnostics to improve the drives diagnostic for Error Rate Check process. (2)Modifications to support drive internal HW changes for component changes. (3)Remove "H0" from the Vital Product Data(VPD).
B011	信頼性向上 Modify the tape drive diagnostics to improve the drives diagnostic for Error Rate Check process.
B010	信頼性向上 Correct rewind/load handling when the tape drive reports cleaning required on a rewind command.
B007	Initial Release

株式会社 日立製作所 エンタープライズサーバ事業部 2009年9月

(c) Hitachi, Ltd. 2009, All rights reserved.