

=====

HITACHI エンタープライズサーバ EP8000 シリーズ マシンコード来歴

=====

DAT オートローダ Firmware 来歴

Firmware レビジョン	変更内容
H003	•First Microcode level shipped.
H008	•Sets time for cleaning indication to 50 hours. •Fixes cases of variable block read failure. •Sets default blocksize of 512.
H210	•Sets default blocksize of 1024. •SCSI Parallel Protocol Request related fixes. •Removal of the 50 usage limit on DDS2 test tapes. •Fixed handing of large number of appending of data causing subsequent space commands over the appended data to fail with an indication of media format corrupted(Sense Key 03, ASC/ASCQ 3100).
H211	•Eliminates SCSI error message on the drive LCD when the drive is powered on with some newer SCSI adapters.

株式会社 日立製作所 エンタープライズサーバ事業部 2006年2月

(c) Hitachi, Ltd. 2004,2006 All rights reserved.